




Garrett Wade

Technical Memo T21

Re: 23N02.01 23N02.02 23N02.10



Special Note: Sometimes the screwdriver on the scribe does not fit the slot of the pivot screw. This can easily be corrected with a small file by removing any burrs left on the tip from the machining process. Simply filing the flats of the tip a few times will correct the problem.

For further assistance, call the Garrett Wade Technical Department at 800 221 2942, or email us at mail@garrettwade.com