



Garrett Wade

Technical Memo T69

Re: 28C01.02

Thank you for your purchase of the Hinged Cordless Driver Kit. The driver has multiple torque settings to ensure the right amount of applied force for the job and comes with 37 driver bits of various type and size.

Charging

Fully charge Driver before first use. To charge, plug the supply connection into the Driver's body. The red indicator light remains on as long as the charger is connected. The battery charge time for the Hinged Cordless Driver is 3 to 5 hours. A full charge should last about 3 days; if the Driver is used only infrequently, it's best to recharge fully before each use. After charging, disconnect the Driver from the charger. To check the amount of remaining charge, press the Battery State Test Button which lights up the Green-Yellow-Red Indicator LEDs.

Operation

The screwdriver controls are a forward/off/reverse 3-position rocker switch, a torque control ring and a work light on/off switch. Keep driver dry and out of the reach of children.

Specifications

Charger Input: 120 V, 60 Hz

Screwdriver Voltage: 4.8 V

Speed: 180 rpm



For further assistance, call the Garrett Wade Technical Department at 800 221 2942, or email us at mail@garrettwade.com