



# Garrett Wade

## Technical Memo T89

Re: 87A01.18 87A01.43

To All Customers of the Miner Style Oil Lamps  
From the Garrett Wade Technical Department

Thank you for your purchase of the Solid Brass Miner-Style Oil Lamp. Always use a refined, high-quality lamp oil or kerosene in your lamp. NEVER use gasoline or any type of spirit or alcohol fuel. For proper care and maintenance of your lamp, please review the instructions below.

### **FILLING INSTRUCTIONS**

Unscrew bottom fuel vessel from the top section with the glass. Unscrew knurled ring surrounding burner. Lift out burner and fill vessel with fuel. Replace burner and screwed knurled ring. Light wick and adjust flame to approximately 1/8" by means of the Wick Pricker Pin. Screw fuel vessel to upper part of lamp and after allowing about one minute for the lamp to achieve air circulation, the flame can be raised to the required height. A flame height of 1/2" is recommended. **NOTE:** Take care to not overfill tank. We suggest  $\frac{3}{4}$  full.

### **CLEANING AND POLISHING**

First apply a light smearing of metal cleaning agent (Brasso, Wenol) and using a dry, soft, clean cloth, rub off briskly to achieve a bright polished finish.

### **WICK MAINTENANCE**

It is important that the wick be cut level with the burner tube, and that the carbon deposit be cleaned off regularly, to ensure a bright light. To dismantle, first unscrew the fuel vessel to expose the brass ring supporting the lamp glass. The ring is slotted and, by means of a suitable forked tool, (a flat headed screw driver can work) it can be unscrewed to release the inner fittings. Care should be taken to see that all parts are replaced in the correct order.

*Garrett Wade Customer Service*

*For further assistance, call the Garrett Wade Technical Department at 800 221 2942, or email us at [mail@garrettwade.com](mailto:mail@garrettwade.com)*